



**Magnetic Digital Level & Angle Locator  
with Dot Laser  
Model No. 40-6065**



# Instruction Manual

*Congratulations on your choice of this Magnetic Digital Level & Angle Locator with Dot Laser. We suggest you read this instruction manual thoroughly before using the instrument. Save this instruction manual for future use.*

This is a Class IIIa laser tool and is manufactured to comply with CFR 21, parts 1040.10 and 1040.11 as well as international safety rule IEC 285. The laser also complies with EMC Test according to EN61000-6-3; 2001+A11:2004, EN 6100-6-1:2011, EN 6100-4-2, EN 61000-4-3, EN 60825, FCC Test according to PART 15.

## Table of Contents

1. Kit Contents	7. Using the Product
2. Features and Functions	8. Self-Check & Fine Calibration
3. Safety Instructions	9. Technical Specifications
4. Location/Content of Warning Labels	10. Care and Handling
5. Location of Parts/Components	11. Product Warranty
6. Operating Instructions	12. Warranty Registration
	13. Trouble Shooting

### 1. Kit Contents

<u>Description</u>	<u>Qty.</u>
“AA” Alkaline Batteries	3
CR2032 Button Battery	1
Soft-sided Pouch	1
Instruction Manual with Warranty Card	1

### 2. Features and Functions

- Displays angle and inclination simultaneously
- Angle measurements in degrees
- Angle inclination in 5 construction languages - units of measure (degrees, percent, mm/m, in/ft in decimal, in/ft in fractional)
- Automatic digit inversion for overhead measurements
- Working range of angle measurement 0 to 182.5°
- Automatic shut-off
- Hold-function to hold measurement
- Visible laser beam to extend working range



### 3. Safety Instructions

Please read and understand all of the following instructions, prior to using this tool. Failure to do so, may void the warranty.

#### ATTENTION



#### IMPORTANT

- Read all instructions prior to operating this laser tool. Do not remove any labels from tool.
- Do not stare directly at the laser beam.
- Do not project the laser beam directly into the eyes of others.
- Do not set up laser tool at eye level or operate the tool near a reflective surface as the laser beam could be projected into your eyes or into the eyes of others.
- Do not place the laser tool in a manner that may cause someone to unintentionally look into the laser beam. Serious eye injury may result.
- Do not operate the tool in explosive environments, i.e. in the presence of gases or flammable liquids.
- Keep the laser tool out of the reach of children and other untrained persons.
- Do not attempt to view the laser beam through optical tools such as telescopes as serious eye injury may result.
- Always turn the laser tool off when not in use or left unattended for a period of time.
- Remove the batteries when storing the tool for an extended time (more than 3 months) to avoid damage to the tool should the batteries deteriorate.
- Do not attempt to repair or disassemble the laser tool. If unqualified persons attempt to repair this tool, warranty will be void.
- Use only original Johnson® parts and accessories purchased from your Johnson® authorized dealer. Use of non-Johnson® parts and accessories will void warranty.

#### DANGER


Class IIIa Laser Product  
Max. Power Output:  $\leq 5\text{mW}$   
Wavelength: 640-660nm

**THIS TOOL EMITS LASER RADIATION.  
DO NOT STARE INTO BEAM.  
AVOID DIRECT EYE EXPOSURE.**





## 5. Location of Part/Components



## 6. Operating Instructions

**IMPORTANT:** It is the responsibility of the user to verify the calibration of the instrument before each use.

### Battery Installation

1. Make sure the instrument is turned off.
2. Open the battery cover. Take out the old batteries and put the new batteries in, paying attention to the polarity.
3. Power on the instrument.

**Note:** Take out the batteries if the instrument is not going to be used for a long time.


### Replacement/Installation of Button Battery

1. If the angle LCD displays “Erro” it is necessary to replace the button battery.
2. Remove the 3 screws on the button battery cover and open battery compartment.
3. Replace the old battery with a new battery.
4. Put the battery cover back on.
5. Check angle calibration.



## 7. Using the Product

### Key Guide



The instrument has six operating keys with their functions below:

#### Power Key

Power on and off the instrument by pressing this key. The instrument will beep twice when turning it on and beep once when turning it off.



#### Laser/Angle Calibration Key

Press and release this key and laser beam will turn on and the laser icon will appear on the LCD. The instrument will also beep once. Press and release this key again and laser beam will turn off and laser icon will disappear on the LCD. **Note:** The instrument must be turned on for the laser beam to work. Press and hold this key (more than one second) and the unit will enter angle calibration mode. See “Self-Check and Calibration” section.





### Slope Calibration Key

The calibration key is used for re-calibrating the instrument in both the horizontal and vertical direction. Refer to Section 8 “Calibration” for details.



### Mode Key

Push the MODE key to switch from one construction language to another. This controls which construction language your electronic module will measure in. Your level has the capability to measure in Degrees, Percentage of slope, Millimeters per Meter, Inches per Foot (Slope, Pitch) in decimal form and Inches per Foot in fractions of an inch. A symbol on the upper right of the screen will explain which MODE you are currently using.



### Sound/Backlight Key

Pressing this key with a short press will turn on the sound function and the sound icon will appear on the LCD. Press and release the key to turn off the sound function and sound icon will disappear on the LCD. The instrument will beep once when turning the sound on and off. The level will beep faster when the level gets closer to 0° and 90° (10°-0° and 80°-90°) when the LCD displays 0° or 90° there will be a continuous tone. Press and hold this key (more than one second) will turn on the backlight.




### Hold Key

The angle readings change in accordance with the change of the incline. Press the key (unit will beep once) to enter into the “hold” mode. The measured angle reading will be held. The display will flash and the angle measurement will not change. Press and release the key again (unit will beep once) will stop the “hold” mode and measured value will change with the incline.







### Automatic Shut-off

This instrument will shut-off automatically if no operation is received within 20 minutes.

### Low-power Indication

The battery symbol will flash on the LCD when the battery power is low. Replace the batteries as soon as possible.

### Incline Indication Arrows



The following figure shows that moving the angle level according to the indicated direction arrows is necessary if you want to position the level to horizontal or vertical.





The following figure shows that the level is level or plumb.






## Locking Arm


When the surface is long, turn the angle level arm to  $180^\circ$ , then tighten the locking screw clockwise. You can lock the arm at any angle within the range of  $0^\circ$  to  $180^\circ$ .



The laser point will be parallel with the reference plane




Measuring the inclining angle to the level plane.





Measuring an angle.



## 8. Self-Check and Fine Calibration


**IMPORTANT:** It is the responsibility of the user to verify the calibration of the instrument before each use.

To guarantee the best measuring precision of the incline, vertical and leveling plane:

- Calibrate before first use.
- Before important measurements.
- After a hit or drop.
- After installing new batteries.

### Horizontal Calibration Check


Put the angle level on a smooth level plane and observe the LCD display. Note the reading after ten seconds. Then rotate the angle level  $180^\circ$  on the same plane. After another ten seconds note the second angle reading. Calibration is necessary if the difference between the two measuring readings is over  $0.2^\circ$ .





### Vertical Calibration Check

Put the angle level on a smooth vertical plane and observe the LCD display. Note the reading after 10 seconds. Then turn the angle level  $180^\circ$  on the same plane. After another ten seconds note the second angle reading. The calibration is necessary if the difference between the two measuring readings is over  $0.2^\circ$ .



### Calibration in the Horizontal Direction


1. Put the level on a flat surface and press the "CAL" button. -0- will be displayed. Wait 10 seconds.
2. Press the "CAL" button again and -1- will be displayed. Turn the level  $180^\circ$  on the same surface. Wait another 10 seconds.
3. Press the "CAL" button once again. If it beeps once the calibration is completed, it is correct. If it beeps twice the calibration is not completed and the procedure should be repeated. If it continues to beep twice the sensor may have been damaged and unit should be serviced.
4. Then do the same thing for the vertical with both the logo on the top and with the logo on the bottom.





## Angle Calibration

1. Place level on a horizontal surface and apply power to product.



2. With angle arm fully closed, press and hold Laser/Cal button until it shows a -1-.



3. Fully open angle arm.



4. Press the Laser/Cal button again to display -2-.  
After about 2 seconds, display should revert back to measuring mode, displaying "180.0°"



5. The angle calibration is completed.  
Verify calibration by closing angle arm.  
Note that right display reads "0.0°"



## 9. Technical Specifications

Laser Wavelength	650nm $\pm$ 10
Laser Classification	Class IIIa
Maximum Power Output	$\leq$ 5mW
Laser Accuracy	$\pm$ 1/8"/50 ft. ( $\pm$ 0.2mm/m)
Working Range Angle	0°-182.5°
Accuracy Angle	$\pm$ 0.1°
Working Range	0° to 90°
Resolution	0.1° or 0.1%
Accuracy	$\pm$ 0.1° for 0° and 90° and $\pm$ 0.2° for 1° to 89°
Power Supply	3 "AA" alkaline batteries and 1 3v CR2032 lithium battery
Battery Life	Approx. battery life 70 hours continuous use
Dimensions	23.6" x 2.48" x 1.57" (600 x 63 x 40mm)
Weight	2.64 lbs (1.2kg)
Working Temperature	14°F to 113°F (-10°C to +45°C)





## 10. Care and Handling

- This laser unit is a precision tool that must be handled with care.
- Avoid exposing unit to shock vibrations and extreme temperatures.
- Before moving or transporting the unit, make sure that the unit is turned off.
- Remove the batteries when storing the unit for an extended time (more than three months) to avoid damage to the unit should the batteries deteriorate.
- Always store the unit in its case when not in use.
- Avoid getting the unit wet.
- Keep the laser unit dry and clean, especially the laser output window. Remove any moisture or dirt with a soft, dry cloth.
- Do not use harsh chemicals, strong detergents or cleaning solvents to clean the laser unit.







## 11. Product Warranty

Johnson Level & Tool offers a three year limited warranty on each of its products. You can obtain a copy of the limited warranty for a Johnson Level & Tool product by contacting Johnson Level & Tool's Customer Service Department, as provided below, or by visiting our web site at [www.johnsonlevel.com](http://www.johnsonlevel.com). The limited warranty for each product contains various limitations and exclusions.

Do not return this product to the store/retailer or place of purchase. Non-warranty repairs and course calibration must be done by an authorized Johnson® service center or Johnson Level & Tool's limited warranty, if applicable, will be void and there will be **NO WARRANTY**. Contact one of our service centers for all non-warranty repairs. A list of service centers can be found on our web site at [www.johnsonlevel.com](http://www.johnsonlevel.com) or by calling our Customer Service Department. Contact our Customer Service Department for Return Material Authorization (RMA) for warranty repairs (manufacturing defects only). Proof of purchase is required.

**NOTE:** The user is responsible for the proper use and care of the product. It is the responsibility of the user to verify the calibration of the instrument before each use.

For further assistance, or if you experience problems with this product that are not addressed in this instruction manual, please contact our Customer Service Department.

In the U.S., contact Johnson Level & Tool's Customer Service Department at 888-9-LEVELS.

In Canada, contact Johnson Level & Tool's Customer Service Department at 800-346-6682.





## 12. Warranty Registration

Enclosed with this instruction manual you will find a warranty registration card to be completed for your product. You will need to locate the serial number for your product that is located inside the battery compartment. **PLEASE NOTE THAT IN ADDITION TO ANY OTHER LIMITATIONS OR CONDITIONS OF JOHNSON LEVEL & TOOL'S LIMITED WARRANTY, JOHNSON LEVEL & TOOL MUST HAVE RECEIVED YOUR PROPERLY COMPLETED WARRANTY CARD AND PROOF OF PURCHASE WITHIN 30 DAYS OF YOUR PURCHASE OF THE PRODUCT OR ANY LIMITED WARRANTY THAT MAY APPLY SHALL NOT APPLY AND THERE SHALL BE NO WARRANTY.**





## 13. Troubleshooting

- If level will not turn on, check the battery polarity or clean the battery terminals and install new, name brand, alkaline batteries.
- If laser will not turn off, press and hold the power button for several seconds until the unit turns off.
- If laser does not illuminate, check the battery polarity or install new, name brand, alkaline batteries and a new 3V button battery (CR2032) and clean the battery terminals.
- If error code, “Erro” appears, install a new 3V button battery (CR2032).
- If laser is out of calibration or numbers are inverted, confirm that the unit is not in “hold” mode. If arrows are blinking on each side of the digital readout, press the “hold” function before attempting calibration. Follow the calibration procedure in the user manual.
- If laser will not calibrate, follow the calibration procedure in the user manual – rotate the level 180°, do NOT flip it upside down.
- If the laser turns off after a short time, clean the battery terminals and install new, name brand, alkaline batteries.
- If the unit will not calibrate, contact an authorized Johnson service center or Johnson Level & Tool’s Customer Service Department.



